

WEST Search History

[Hide Items](#) | [Restore](#) | [Clear](#) | [Cancel](#)

DATE: Thursday, January 19, 2006

<u>Hide?</u>	<u>Set Name</u>	<u>Query</u>	<u>Hit Count</u>
<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L59	156 and mask	105
<input type="checkbox"/>	L58	155 and mask	309
<input type="checkbox"/>	L57	153 and (716/4[ccls] or 716/19[ccls] or 716/20[ccls] or 716/21[ccls])	115
<input type="checkbox"/>	L56	153 and 716/\$[ccls]	124
<input type="checkbox"/>	L55	153 and l32	486
<input type="checkbox"/>	L54	("characteristic dimension" or "critical dimension") with ("measurement position?" or "measuring position?")	15
<input type="checkbox"/>	L53	("characteristic dimension" or "critical dimension") with measur\$	2183
<i>DB=USPT,PGPB; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L52	('4191462' '5170293' '5840448' '5867276' '5963329' '6115108')![pn]	6
<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L51	L50 and (716/\$[ccls] or 700/\$[ccls] or 702/\$[ccls] or 382/\$[ccls])	26
<input type="checkbox"/>	L50	L49 and (position\$ with accuracy)	198
<input type="checkbox"/>	L49	L48 and mask	1981
<input type="checkbox"/>	L48	SEM with measur\$	6212
<i>DB=USPT,PGPB; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L47	('5933350' '6622295' '20020143424' '20020143650' '20020161665' '20030177469')![pn]	6
<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L46	L45 and L32	24
<input type="checkbox"/>	L45	L42 and ((accuracy with measur\$) same mask)	217
<input type="checkbox"/>	L44	L42 and (accuracy with measur\$)	4606
<input type="checkbox"/>	L43	L42 and measur\$	31393
<input type="checkbox"/>	L42	L37 or L38	42604
<input type="checkbox"/>	L41	L40 and mask	54
<input type="checkbox"/>	L40	L39 and L32	138
<input type="checkbox"/>	L39	L38 and L37	426
<input type="checkbox"/>	L38	"quality control"	35873
<input type="checkbox"/>	L37	metrology	7157
<input type="checkbox"/>	L36	6711453[pn] or 6631511[pn]	2
<input type="checkbox"/>	L35	6711453[pn] or 6637511[pn]	2

<input type="checkbox"/>	L34	L32 and L29	120
<input type="checkbox"/>	L33	L32 and L28	18
<input type="checkbox"/>	L32	L6 or L18 or 702/\$[ccls] or 382/\$[ccls]	103047
<input type="checkbox"/>	L31	L29 not "cd-rom"	496
<input type="checkbox"/>	L30	L29 and L28	18
<input type="checkbox"/>	L29	L3 and ("critical dimension" or cd)	823
<input type="checkbox"/>	L28	L3 and "structural element"	186
<input type="checkbox"/>	L27	L18 and L11	6
<input type="checkbox"/>	L26	L24 and L4	0
<input type="checkbox"/>	L25	L24 and L3	2
<input type="checkbox"/>	L24	"exchange file"	674
<input type="checkbox"/>	L23	L4 and L21	0
<input type="checkbox"/>	L22	L3 and L21	2
<input type="checkbox"/>	L21	"memory cell field"	557
<input type="checkbox"/>	L20	L3 and metrology	310
<input type="checkbox"/>	L19	L18 and L10	12
<input type="checkbox"/>	L18	700/\$[ccls]	29630
<input type="checkbox"/>	L17	L16 and lithograph\$	28
<input type="checkbox"/>	L16	"zoom-ins"	1278
<input type="checkbox"/>	L15	L11 or L10	592
<input type="checkbox"/>	L14	L11 and L10	46
<input type="checkbox"/>	L13	L11 and L6	1
<input type="checkbox"/>	L12	L10 and L6	2
<input type="checkbox"/>	L11	"measuring position?" with communicat\$	195
<input type="checkbox"/>	L10	"measuring position?" with transmit\$	443
<input type="checkbox"/>	L9	L8 or L7	31
<input type="checkbox"/>	L8	L6 and L4	17
<input type="checkbox"/>	L7	L6 and L3	17
<input type="checkbox"/>	L6	716/\$[ccls]	9379
<input type="checkbox"/>	L5	xtarget	38
<input type="checkbox"/>	L4	"measurement position?"	7716
<input type="checkbox"/>	L3	"measuring position?"	10344
<input type="checkbox"/>	L2	6457168[pn] or 20020083408	2
<input type="checkbox"/>	L1	20040131950 or 6586308[pn]	2

END OF SEARCH HISTORY